#### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

## WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-002751 Address: 333 Burma Road **Date Inspected:** 29-Apr-2008

City: Oakland, CA 94607

**OSM Arrival Time:** 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1700 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name:** Sun Wei **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes N/A **Delayed / Cancelled:** No

**Bridge No:** 34-0006 **Component: Deck Panels** 

#### **Summary of Items Observed:**

The Quality Assurance (QA) Inspector, Mahlon Lindenmuth, arrived on site at the Zhenhua Port Machinery Company facility on Changxing island, China to periodically monitor welding and Quality Control functions. While on site the Quality Assurance Inspector observed and/or discovered the following.

#### Bay 3 – New Tower Building

The QA Inspector randomly observed ZPMC welding and quality control personnel performing inspection, grinding, and Flux Core Arc Welding (FCAW) repairs of deck panel Partial Joint Penetration (PJP) welds. The deck panels in repair process are designated as:

DP014-001

DP003-001

DP055-001

Repairs of all areas marked, on the above Deck Panels has not been completed on this date. Some areas of repair required remarking (paint stick) due to the Deck Panels being exposed to the elements outdoors.

There are currently thirteen (13) Deck Panels stored in Bay 3 awaiting repairs.

QA Lindenmuth began developing a new log for tracking repairs done to the Deck Panels. The developement of the tracking log was then given to QA Inspector, Willian Clifford, for completion.

### **Summary of Conversations:**

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)

## **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

Inspected By:	Lindenmuth, Mahlon	Quality Assurance Inspector
Reviewed By:	Cuellar,Robert	QA Reviewer